



Georgia Structural Pest Control Commission

Chris Gorecki, Chairman
Derrick Lastinger, Vice-chairman
Christy Kuriatnyk, Georgia Department of Public Health
Dr. Brian Forschler, University of Georgia
Bodine Sinyard, Adams Exterminators
Greg Holley, Zone Pest Solutions
Kim Bragg, Consumer Affairs & Protection Representative

December 13, 2019

Mr. Ted Miltiades
The Department of Community Affairs
Codes and Industrialized Buildings Section
60 Executive Park South, NE
Atlanta, Georgia 30329-2231

Please accept the attached proposed state code amendment and supporting documents. The amendment is submitted on behalf of the members of the Georgia Structural Pest Control Commission (SPCC). The SPCC serves the public and the professional pest management industry by promulgation of appropriate Rules of the Georgia Structural Pest Control Act, advising the Georgia Department of Agriculture on enforcement concerns and ensure the proper licensing of pest management companies, certification of operators and registration of employees.

Please do not hesitate to use the SPCC as a resource. Thank you for your consideration.

Sincerely,

Chris Gorecki, Chairman
Georgia Structural Pest Control Commission

GEORGIA DEPARTMENT OF COMMUNITY AFFAIRS

CODE AMENDMENT FORM

ITEM NO: _____ (DCA USE ONLY) PAGE 1 OF 2

CODE: IECC SECTION: R402.2.9

PROPOSER: Georgia Structural Pest Control Commission DATE: 12/13/19

EMAIL: SPCC@agr.georgia.gov

ADDRESS: 19 Martin Luther King, Jr. Dr., S.W. Atlanta, Georgia 30334

TELEPHONE NUMBER: (404)656-3641 FAX NUMBER: 404)463-6671

CHECK Revise section to read as follows: Add new section to read as follows:
ONE: Delete section and substitute the following: Delete without substitution:

~~LINE THROUGH MATERIAL TO BE DELETED:~~ UNDERLINE MATERIAL TO BE ADDED

Approve Approve as amended (DCA STAFF ONLY) Disapprove Withdrawn

DESCRIPTION:

R402.2.9 Crawl space and Basement walls.

As an alternative to insulating floors over crawl spaces, crawl space walls shall be permitted to be insulated when the crawl space is not vented to the outside. Crawl space and basement wall insulation shall be permanently fastened to the foundation wall. ~~and extend downward from the floor to within 9 3 inches (76 mm) of the finished interior grade adjacent to the foundation wall.~~ A 3-inch (76 mm) inspection/view strip immediately below the floor joists at the top and bottom of the foundation wall shall be provided to permit inspections for termites. The band joist and mudsill shall be air sealed then insulated with a removable insulation product to provide for pest control inspection of the wood framing members.

Exposed earth in unvented crawl space foundations shall be covered with a continuous Class 1 clear/non-opaque vapor retarder in accordance with the International Building Code. All joints of the vapor retarder shall overlap by 6 inches (152 mm) and be sealed or taped. The edges of the vapor retarder shall extend at least 6 inches (228 mm) up the stem wall and shall be attached and sealed to the stem wall behind the insulation.

REASON/INTENT:

The Georgia building code requires 3" termite inspection gaps at the top and bottom of the foundation wall, but allow the band joist and mudsill to be covered with permanently fastened insulation, such as spray polyurethane foam, (SPF). However, the installation of SPF on the band joist and mudsill covers the critical areas that the pest management companies need to visually inspect. The mudsill, band joist and joist ends are the first points at which termites can be detected as they enter the wood structure. Subterranean termites can pass through small - 1/64" cracks and gain access to structural lumber by constructing shelter tubes and climbing up the inside or outside of the foundation wall. Termites can also

enter buildings through cracks in the footing and travel through voids in concrete masonry units. Inspection opportunities from the exterior of the building are often obstructed by brick or landscaping features, so inspection from inside the crawlspace is the only option. There are currently no alternative “viable” inspection methods or tools available to perform the inspections through SPF. This amendment will provide for termite inspections, insulation and air sealing in the band joist area.

FINANCIAL IMPACT OF PROPOSED AMENDMENT:

This amendment will take some extra time but will allow for the periodic inspections required to maintain termite warranties/bonds. Additionally, Georgia consumers will be able to take advantage of both valuable services, SPF and termite control.

Spray Foam Insulation and Subterranean Termite Inspection Issues

As building performance requirements have steadily increased to provide lower energy consumption, reduced air leakage, improved moisture management and building durability, the use of Spray Polyurethane Foam Insulation, (SPF) has grown significantly. This has created issues between the SPF industry and pest management companies.

Termites cause more than \$5 billion in structural damage each year in the United States. As part of the termite management process, inspections are performed by trained personnel at various points in the termite management process. Inspections may be performed to identify termite infestation and determine necessary control procedures, as part of a periodic, ongoing warranty/bond programs designed to detect and manage termite infestations (and re-infestations) as early as possible, and as part of real estate transfers (many state rules and all HUD/FHA guaranteed loans and many private lenders in most regions of the U.S.). Successful termite inspections are dependent on having visual access to identify evidence of infestation.


In the regions where subterranean termites are active, as shown in 2015 IRC Table R301.2.(6), (Figure 1), the use of SPF has created an issue with termite inspections. The areas of the building where SPF most commonly interferes with subterranean termite inspections are basement and crawl spaces in which SPF has been installed on the foundation walls, the mud sill and band joist areas. This assembly is known as a sealed or semi-conditioned crawl space, which requires the assembly to be insulated and have a continuous air barrier installed by code. The building industry has increasingly moved to using SPF to achieve its insulation and air barrier objectives. Building codes in Georgia and a few other states (NC, AL & MS) require 3" termite inspection gaps (no foam) at the top and bottom of the foundation wall, but still allow the band joist and mudsill to be covered with SPF. However, the installation of SPF on the band joist and mudsill covers the critical areas that the pest management companies need to visually inspect. The mudsill, band joist and joist ends are the first points at which termites can be detected as they enter the wood structure. Subterranean termites can pass through small 1/32" to 1/64" cracks and gain access to structural or decorative lumber by constructing shelter tubes and climbing up the inside or outside of the foundation wall. Termites can also enter buildings through cracks in the footing and traveling through voids in concrete masonry units. Inspection opportunities from the exterior of the building are often obstructed by brick or landscaping features, so inspection from inside the crawlspace is the only option. There are currently no alternative "viable" inspection methods or tools available to perform the inspections through SFF (see attachment "A": "Spray Polyurethane Foam / Termite Detection Demonstration Project" completed by Dr. Brian Forschler, University of Georgia, Athens GA). Additionally, visual inspections are required by some states and mortgage companies.

A result of this issue has been that homeowners who retrofit their vented crawl spaces to unvented (semi-conditioned) to improve energy and moisture management performance, may be put in a situation that their existing termite bonds or warranties are cancelled. This is due to the fact that the spray foam was installed according to building code requirements but covering the band joist and mudsill prevents termite inspectors from detecting subterranean termite infestations. New construction, based on the building codes can also have the same

outcome, taking away the pest management industry's ability to inspect this crucial area. The Georgia Structural Pest Control Commission (GA SPCC) issued SPCC Notice: 18-04 Spray Foam Insulation & Pest Management on 6/20/18 (see attachment "B") which provides Georgia consumers with important information related to ***Polyurethane Spray Foam Insulation***.


The overall solution to improve building performance and permit visual termite inspection is to provide the code required 3" inspection gaps on the top and bottom of the foundation wall and prohibit the installation of spray foam over the band joist and mudsill. The framing members would need to be caulked at the joints connecting the floor sheathing above, to the top of the foundation, as can be seen on Drawing 1. A non-rigid, removeable insulation, such as a fiberglass batt, would then be placed in the "pocket" to insulate the band joist and the mudsill. This will take extra time but will allow for the periodic inspections required to maintain termite warranties/bonds. Additionally, consumers will be able to take advantage of both valuable services, SPF and termite control.

Figure 1. 2015 IRC Table R 306.1.2 (6) Subterranean Termite Map



Drawing 1

Unvented/Sealed Crawlspace with 1.5 +” Closed Cell Spray Foam on Foundation Wall and Removable Insulation on Band Joist



Spray Polyurethane Foam / Termite Detection Demonstration Project (July – August 2019)

Introduction

The Demonstration Project described in this report was an attempt to gather information on the utility of identifying subterranean termite infestations in or on structural components covered with Spray Polyurethane Foam (SPF) insulation. The project was conducted in a crawlspace with an active infestation of the dark southeastern subterranean termite, *Reticulitermes virginicus*. The crawlspace had hollow-block foundation walls and piers with wood framing above that which served as the support for the rooms on the first floor of the structure. Initial inspections were conducted on July 16, 2019 using visual search, moisture meters, infrared cameras, a laser thermometer and a microwave motion detector. Five inspectors, identified herein by number (1-5) each used a different approach. Inspector #1 conducted a visual search in conjunction with a moisture meter; #2 used visual inspection and an infrared camera; #3 used visual inspection, a moisture meter and motion detector; #4, moisture meter, borescope and infrared camera; and #5 used visual inspection, moisture meters and an infrared thermometer. Inspectors were given one hour to examine the crawlspace and place laminated cards (red arrow) at locations where they identified termite activity. The distribution of red arrows was recorded by photography after each inspection. Inspectors then agreed to 6 locations where SPF insulation would be applied to the hollow-block foundation wall (two locations) and wooden structural members (four locations) in the crawlspace. The application of SPF at each Location included half of the designated area covered using closed-cell (2-3 inches thick) and the other half open-cell (4-6 inches thick) SPF. The following day, 17 July, the crawlspace was for a second time inspected by the same teams using the same equipment and the number and distribution of red arrows recorded for comparison with the previous inspections. One month after SPF application, 15 August, an additional inspection was conducted by all parties after which destructive sampling was conducted to verify the presence of live termites at all Locations examined in this demonstration project.

Building: River Basin Center, School of Ecology, University of Georgia, Athens, GA 30602

Areas Inspected: Crawlspace in the north east corner of the structure

Site Description: The crawlspace measured 20X20X20X10-ft and was installed during a renovation of the building in 1999 (Figure 1). The crawlspace was defined by hollow block walls approximately 7-ft high with wood framing for the floor with four hollow block piers and one metal pole as supports for the floor in the center of the space. A vapor barrier was placed over the soil floor of the crawlspace on July 15, 2019.

Description of equipment used by inspector (number) and equipment (type, model):

All inspectors had at least 20 years' experience conducting termite inspections. The firm that applied SPF has been in business for 5 years and has a A+ BBB rating.

#1, Ryobi, E49MM01 resistance (surface with digital readout in %) and Protimeter Mini (BLD2001) a pin-type (subsurface with light-up scale in 1% increments from 6-30) moisture meters

#2, Infrared camera, FLIR E6

#3, Termatrac T3i All Sensor 3-n-1 unit with the following functions, Radar Technology confirms movement, Moisture sensors both Direct & Relative using Omni-Directional Technology (digital readout in %) and Thermal Sensor showing changes in surface temperature.

#4, Infrared camera, Protec IT 100; A moisture meter, Protimeter moisture meter system-logging MMS2 (digital readout in %) and a XLVU Videoprobe (a flexible borescope), Baker Hughes Co.

#5, Infrared thermometer, General IRT207, and two moisture meters; Tramex moisture encounter resistance (surface, range in 1% increments on a graph from 10-20%) and Delmhorst Instrument Co. PC-3 pin-type (subsurface, range in 2% increments that light-up display measuring from 8-30%).

Initial Inspection notes, 16 July:

The wooden structural members - joist header, sill plate, joists and cross beams - in the crawlspace provided numerous locations where visual evidence of subterranean termite infestation was clear and obvious. There also were 10 areas with subterranean termite shelter tubes on the exterior surface of the concrete block foundation.

All 5 inspectors collectively placed 38 red arrows in the crawlspace during the initial inspection in the area adjacent to the entryway along 40 feet of foundation wall from the southeast corner to the northwest corner of the crawlspace (Locations 0, 15, 20, 30 and 35 38). The range of arrows placed per inspector was 3 to 14 (Table 2).

Surface temperatures on all substrates – block or wood – did not vary more than 0.9 degrees Celsius (1.6 degrees Fahrenheit) between any of the surfaces in the crawlspace with no pattern related to signs of termite activity. The Flir IR camera identified 1 area of termite activity on wood (Location 15) (Photograph 2) and 2 other termite-activity areas were associated with shelter tubes at Locations 0 & 40.

The moisture readings obtained on the wooden floor joists, headers and sill plates indicated elevated moisture in all the wood in the crawlspace. Depending on the type of meter and location readings ranged from 18-30% wood moisture using resistance (surface) meters to 20-30% wood moisture using a meter with insertion pins (subsurface). The resistance/surface moisture meters provided readings of 20-50% when placed on the surface of the cinder block

foundation while one pin-type meter registered 100% on the block when pins were placed against the surface of that material.

The Termatrac T3i microwave motion detector identified notable movement in the shelter tubes at locations 0 and 20 as well as in the beams and sill plate at locations 5 and 15 but not 25 or 30. No live termites were observed at any location despite destructively sampling a 1-2 inch section of shelter tube at locations 0, 20 and 40 (Location 40 was on the north wall but not indicated in Figure 1). There was no destructive sampling of any of the wood supports on this inspection.

SPF foam was applied to the shelter tubes at locations 0 and 20 and on the sill, joist header and beams at locations 5, 15, 25 and 30 (Photograph 1; Figure 1). Two types of SPF were applied at each location, closed cell SPF at 2-3 inches and open cell SPF at 6-8 inches thick.

Inspection notes after SPF application; 17 July:

The number of red arrows placed on the exposed wood by all 5 inspectors was 39 the day after SPF application (Table 2). None of the visual inspections provided evidence of termite activity on the SPF (Table 2). The only device that detected termites through the SPF was the Termatrac T3i microwave motion detector which identified 6 locations (red arrows placed) on the SPF (Table 2). The Termatrac T3i identified movement in shelter tubes at 5 areas including Locations 0 and 20 as well as the beams and sill plate at Locations 5, 15 and 30... but not 25 (Table 1 & 2).

Surface temperatures on the block wall and structural lumber varied by 1.9 degrees Celsius (3.6 °F) and on foam by 0.9 degrees Celsius with no pattern related to signs of termite activity (Table 1). There were no areas of termite activity identified by the IR cameras on SPF or exposed wood or block.

Moisture readings obtained on the foundation wall, floor joists, headers and sill wood provided the same range of values, by device, measured on inspections conducted the previous day, July 16 (Table 1). Moisture readings on the SPF surface with resistance meters was zero while the pin meters ranged from 2-4% on the surface but registered 0-8% when pins were inserted into either the open- or closed-cell foam. The Termatrac T3i measures of moisture on foam varied from 4-11% with no identifiable pattern related to areas of termite activity.

No live termites were observed at any location and the sections of shelter tubes at locations 0, 20 and 40 that were broken during the previous inspection, on day earlier, had not been repaired. There was no destructive sampling on this inspection.

Inspection notes one-month after SPF application; 15 August:

Inspections aimed at determining termite activity were not recorded during the August visit to the crawlspace due to time constraints and the assumption that those results would be similar to the previous two inspections. Initial visual inspections did not reveal signs of termite activity on the foam but as SPF removal progressed (Photograph 3) it was observed that one area of closed cell foam (at Location 5) on the interface of the sill plate and foundation wall showed signs of termite activity (Photograph 4). When SPF was removed from the block covering the shelter tubes at locations 0 and 20 there were live termites in the shelter tubes but no evidence of

termites leaving the shelter tubes and entering the foam. Termites did, however, tunnel into the foam on the beams, joist header and sill at locations 5 and 15 and but not areas 25 or 30 (Photograph 3). There were hundreds of live termites in the foam removed from the aforementioned areas and live termites also were observed in the sill and beams at areas 5 and 15 by destructive sampling and with the borescope (Photograph 5).

Surface temperatures on wood varied by 1.9 degrees Celsius and on foam 0.9 degrees Celsius with no pattern related to signs of termite activity (Table 1).

The range of moisture readings on wood were within the range of values from one month earlier for each of the different devices. The one exception was the Termatrac readings that were, across all locations, higher than in the previous month. The moisture readings on the block were essentially within the same range within a device but showed more variability compared to the previous month with the Termatrac T3i and Delmhorst being higher while the Tramex provided lower values. All devices recorded significantly higher wood moisture content in the joists and joist header that had been under the SPF except the Termatrac which provided lower wood moisture content in those areas (Table 1).

Moisture readings were taken on the area of visible termite activity in the SPF at location 15 and the only device that provided a different reading was the Termatrac T3i that showed 9-15% on the foam next to the area of visible activity and 17-23% on top of that location (Photograph 6).

In addition, we used a XLVU Videoprobe borescope to verify termite activity in the wood behind Locations 5 and 15 as well as demonstrate that this device could also distinguish between infested and not-infested foam (Photograph 5).

Summary:

This SPF/termite-detection demonstration aimed to examine the ability of pest management professionals, experienced in termite inspections, to identify an active termite infestation in the same crawlspace before and after application of SPF insulation. The site was a crawlspace with a moisture problem as evidenced by the wood % moisture recorded with all moisture meters used by the inspectors (Table 1).

The results from the visual inspections included the obvious, intuitive, observation that visual inspection was prevented following application of SPF to either the wood or hollow cinderblock construction materials (Table 2). Visual inspections are subjective, and inevitability, grounded in the experience of the individual inspector and circumstances at the time and place of the inspection. This point is evident in the summary of the number of red arrows placed by each inspector on the first two inspection dates (Table 2). The number of points identified (with red arrows) using visual search between inspectors indicating evidence of termite activity clearly underscores the aforementioned subjectivity. The fact that three experienced termite inspectors went to the same crawlspace and identify three different number of 'active locations' indicates the experiential nature of reporting termite activity using visual inspection. The number of different locations identified by each inspector could have been a result of the fact that evidence of termite activity was widespread in that crawlspace (Photographs 1 & 2). The purpose of an

inspection is typically to justify an intervention and one inspector could have placed 3 arrows in an area (split hairs) where the next inspector would have placed 1 because those locations all indicated need for intervention within a section of sill or joist.

Temperature readings taken on the surfaces in the crawlspace displayed surprising similarity regardless of substrate with never more than a ± 2 degrees Celsius difference between the wood, block or foam surface temperatures (Table 1). The fact that those temperature differences were within the range of detection for both IR cameras used in this demonstration and it is therefore not surprising those devices were not able to detect the presence of termites with or without a covering of SPF.

An equally interesting, but less obvious, result involved the moisture meters which provided a wide range of values at the same locations (Table 1) indicative of the relative nature of measurements taken by these instruments, depending on the device and technology used to translate electrical conductivity to a number representing percent moisture. All moisture meters with the exception of the Termatrac T3i were consistent with the surface-type meters generally providing no readings on the foam surface while the pin-type moisture meters provided low readings (0-8% moisture) when inserted into the foam. The Termatrac T3i moisture readings ranged from 4-11% the day after SPF application to 0-26% one month later (Table 1).

The conclusion we were able to reach, given the parameters that defined this demonstration project is that the devices employed by the participants were unable to identify any consistent indication of termite infestation on the wood or block and certainly not *through* the SPF insulation. Additional research under varying conditions should be conducted to see how these same or other termite detection devices perform. The Termatrac T3i was the only device to provide moisture readings (17-23%) on the area of closed cell SPF with visual confirmation of termite activity that was different from the surrounding foam (14-15%) (Photograph 6).

The Termatrac T3i using the microwave motion detector provided evidence of termite activity with and without the foam (Table 1). Confirmation of termite activity was confined to the last (August) inspections when destructive sampling was conducted. There were no live termites found during the July inspections when shelter tubes at Locations 0 & 20% were broken nor where those sections of shelter tube repaired (after SPF application) the following day. However, one month after SPF application (August inspection) thousands of termites were observed in the foam and in pieces of wood destructively sampled with a chisel and the borescope as well as in shelter tubes at Locations 0 & 20 (Photographs 3- 5). Destructive sampling using the borescope provided evidence that by drilling 1/4-inch holes into SPF one can determine if termites are present (Photograph 5).

Postscript and Conclusions:

Renovation of the crawlspace used in this demonstration began on 6 September 2019. The sill plate, joist header, floor joists and flooring were removed from the foundation walls above the crawlspace entry and halfway down the length of the southern-most wall of the crawl. The renovation exposed the foundation wall behind the joist header and sill plate above Locations 0, and 5 mentioned in the report. An examination of the exposed elements of the foundation

provided substantial evidence that this infestation was initiated in the sill and joist headers in the southeast corner of the crawlspace. The amount of termite feeding activity observed in the joist header, sill and floor joists (Photograph Supplement 1) in that area displayed a pattern showing more wood removed from structural lumber closer to the SE corner of the crawlspace.

Subterranean termite structural infestations can be influenced by numerous factors including the construction practices employed – especially the elements of the foundation - as well as the surrounding landscape. This particular infestation was most likely exacerbated by the limited potential for air exchange in the crawlspace. This ~ 300 square-ft section of the structure contained two vents (12 X 8-in.), both in the north wall, coupled with no vapor barrier on the dirt floor of the space (it should be noted that during the September renovations it was discovered that there was a concrete slab floor in the crawlspace... under about 4 inches of soil). The higher- than-normal % wood moisture (The author defines ‘normal’ structural lumber % moisture to be 9-12% for this part of North Georgia) in the lumber of the crawlspace measured using moisture meters affirmed this point as did the observations of mold made by all inspectors conducting a visual search.

Inspection of any structure for subterranean termite activity is essentially a snap-shot in time of conditions observed during a site visit and the information recorded during this demonstration illustrates that point. The findings reported from a termite inspection are influenced by a number of factors including the type of equipment employed during the inspection. The variability reported within a single technique or piece of equipment between inspection dates shows that termite inspections can agree on the presence of termite activity although the data used to come to that conclusion might be disparate.


A visual inspection was sufficient to identify signs of a termite infestation and moisture management issues in this crawlspace. Verification of an active termite infestation and moisture problems required additional techniques and equipment. The industry standard of a visual inspection along with probing and sounding (i.e. destructive sampling) to verify an active infestation was not conducted until the third (August) inspection. The various moisture meters, indicated on the first and subsequent inspections, conditions of elevated wood moisture which would be conducive to maintaining a subterranean termite infestation. However, the moisture meters alone could not verify areas of active termite infestation. The technique employed (as per the protocol requirement of minimal disturbance) to verify termite activity during the first inspection – a visual inspection after exposing a small section of several of the numerous shelter tubes in this crawlspace - did not provide evidence of active termites. Subterranean termite activity was only confirmed during the August inspection using destructive sampling.

There were two non-destructive termite inspection technologies used during the inspections. The homogeneity of surface temperatures on all the substrates (wood, block or SPF) did not allow for a clear, definitive identification of termite activity using an IR camera. The Termatrac T3i microwave motion detector did indicate an active infestation at a number of Locations on all three inspections on all substrates examined – shelter tube on hollow block, structural wood, and SPF. Those indications of activity were verified during the August destructive sampling inspection.

The veracity of using visual inspection along with probing to identify an active subterranean termite structural infestation was confirmed by this demonstration project. The project also illustrated that SPF foam applied to structural lumber prevented a visual inspection of termite activity. The utility of moisture meters and IR cameras in identifying termite activity with or without SPF was not confirmed. The microwave motion detection device, Termatrac T3i, demonstrated the ability to detect termite activity in structural lumber with and without a covering of SPF. There are, however, practical limitations to conducting a termite inspection using the Termatrac T3i because it can detect motion in a relatively small (4 inches squared) area. Restricting the collection of termite inspection data to the scale of 4 inches² would require hours to complete a full inspection of the 300 ft² crawlspace used in this demonstration. The utility of using a device with such a small inspection 'window' complicates conducting a full termite inspection due, in part, to the increased time spent on site.

Acknowledgements. The author extends his sincere thanks all the professionals who donated their time, equipment and expertise during this demonstration. The project could not have been conducting without their generosity and I am indebted and deeply appreciative of their sacrifice. The participants included: Rick Bell, Arrow Exterminators; Brian Forschler, University of Georgia; Heath Knudsen and David Eubanks, Flexible Pest Services; Ed Freytag, New Orleans Mosquito and Termite Control Board; Rick Wakenigg, Termatrac LLC; Josh Nichols and Ryan Drueke and Josh Nichol, Foam South insulators.

Figure 1. Diagram of the crawlspace from the building floor plan with blue lines delimiting the interior foundation walls that define the crawl, green lines approximate distances (in feet) of the crawlspace foundation and the red line indicates the location of doorway providing access to the crawlspace. The Location numbers discussed in the report are posted in white boxes in red font with Locations O and 20 on the hollow block wall in the south east and southwest corners, respectively, and Locations 5, 15, 25, and 30 on the joists and joist headers on the south and west walls, respectively.



Photograph 1. Images of the locations discussed in the report where SPF was applied.

A. Locations 0 (not identified with a number; in the corner) and 5.

B. Locations 15, 20, 25, 30.

A.



B.



Photograph 2. Image of the IR camera screen (Flir E6) indicating an area determined to show termite activity during the first inspection (July, 17) and a visual image of the same area indicated by the red box (right).



Photograph 3. Images of termite activity in the SPF observed during the August inspection from the joists and joist header by Location 5.



Picture 4. Images of the area in the SPF at Location 5 that provided visible evidence of termite activity on surface of SPF... left (outlined by the red box) and that same area exposed during foam removal.



Photograph 5. Images from the borescope showing SPF without (left) and with (right) termite activity.



Photograph 6. Image of the Termatrac T3i percent moisture readings on closed-cell foam at Location 5 on the block in an area with (left) and without (right) termite activity.




Table 1. The record of data collected in the crawlspace by date, instrument and location. A single number indicates the 2-3 readings within 1-ft² were consistent while a range is a record of the high and low reading for that instrument at that location. NA indicates “Not Applicable”.

A. Readings taken July 16, 2019 prior to application of foam.

Meter type	Location Zero (on block)		Location 5 (on wood beam)		Location 5 (on wood sill)	
	On SPF	w/o SPF	On SPF	w/o SPF	On SPF	w/o SPF
Delmhorst	NA	26	NA	20	NA	20
Protimeter	NA	30	NA	20	NA	24
Protimeter 2	NA	100	NA	18-20	NA	25-30
Tramex	NA	20+	NA	20+	NA	20+
Ryobi	NA	50	NA	30	NA	22
Termatrac T3i	NA	25-26	NA	19	NA	25
Laser temp °C	NA	27.2	NA	26.6	NA	26.5
Termatrac T3i motion detector	Termatrac found movement on tube but no live termites seen in small section of broken tube		Termatrac found movement but no live termites seen, no destructive sampling		Termatrac found movement but no live termites seen, no destructive sampling	

Meter type	Location 20 (on block)		Location 15 (on wood beam)		Location 15 (on wood sill)	
	On SPF	w/o SPF	On SPF	w/o SPF	On SPF	w/o SPF
Delmhorst	NA	20	NA	20	NA	20
Protimeter	NA	17	NA	22	NA	24
Protimeter 2	NA	100	NA	18-20	NA	25-30
Tramex	NA	20+	NA	20+	NA	20+
Ryobi	NA	33	NA	26	NA	34
Termatrac T3i	NA	25	NA	18	NA	24
Laser temp °C	NA	26.3	NA	26.8	NA	26.4
Termatrac T3i motion detector	Termatrac found movement on tube but no live termites seen in small section of broken tube		Termatrac found movement but no live termites seen, no destructive sampling		Termatrac found movement but no live termites seen, no destructive sampling	

B. Readings taken July 17, 2019 one day after application of foam.

Meter type	Location Zero (on block)		Location 5 (on wood beam)		Location 5 (on wood sill)	
	On SPF	w/o SPF	On SPF	w/o SPF	On SPF	w/o SPF
Delmhorst	0	26	0	20	0	20
Protimeter	1	100	2-4	19-22	0-2	24
Protimeter 2	4-6	68	4-6	18-20	4-6	17-20
tramex	0	20+	0	20+	0	20+
Ryobi	0	50	0	30	0	22
Termatrac T3i	4-11	25-26	4-11	19	4-11	25
Laser temp °C	26.7	25.9	26.4	26.8	26.5	26.4
Termatrac T3i motion detection	Termatrac found movement on tube but no live termites seen in small section of broken tube		Termatrac found movement but no live termites seen, no destructive sampling		Termatrac found movement but no live termites seen, no destructive sampling	

Meter type	Location 20 (on block)		Location 15 (on wood beam)		Location 15 (on wood sill)	
	On SPF	w/o SPF	On SPF	w/o SPF	On SPF	w/o SPF
Delmhorst	0	20	0	20	0	20
Protimeter	3-6	17	3-6	22	3-6	24
Protimeter 2	4	100	4-8	18	4-8	25-30
tramex	0	20+	0	20+	0	20+
Ryobi	0	33	0	26	0	34
Termatrac T3i	4-11	25	4-11	18	4-11	24
Laser temp °C	26.5	26.4	26.5	26.5	26.4	26.5
Termatrac T3i motion detection	Termatrac found movement on tube but no live termites seen in small section of broken tube		Termatrac found movement but no live termites seen, no destructive sampling		Termatrac found movement but no live termites seen, no destructive sampling	

C. Readings taken August 15, 2019 one month after application of foam prior to foam removal.

Meter type	Location Zero (on block)		Location 5 (on wood beam)		Location 5 (on wood sill)	
	On SPF	w/o SPF	On SPF	w/o SPF	On SPF	w/o SPF
Delmhorst	0	30+	0	20	0	24
Protimeter	0	14-17	2	20	0	24
tramex	0	17.5	0	20+	0	20+
Ryobi	8-16	33	12	26	14	34
Termatrac T3i	14-20	30+	7-26	30+	12-20	30+
Laser temp °C	26.5-27	26.7	27.8	28.2	27.1	27.4
Termatrac T3i motion detector	Termatrac found movement through foam and on tube. Live termites seen during destructive sampling		Termatrac found movement through foam. Live termites seen during destructive sampling		Termatrac found movement through foam. Live termites seen during destructive sampling	

Meter type	Location 20 (on block)		Location 15 (on wood beam)		Location 15 (on wood sill)	
	On SPF	w/o SPF	On SPF	w/o SPF	On SPF	w/o SPF
Delmhorst	0	24	0	20	0	24
Protimeter	0	15-18	0	20	0	22
tramex	0	18	0	20+	0	20+
Ryobi	0	51	16	24	0	32-34
Termatrac T3i	9-15	30+	0-16	30+	14	30+
Laser temp °C	27/26.5	27.3	26.9	26.8	27	26.3
Termatrac T3i motion detector	Termatrac found movement through foam and on tube. Live termites seen during destructive sampling		Termatrac found movement through foam. Live termites seen during destructive sampling		Termatrac found movement through foam. Live termites seen during destructive sampling	

D. Readings taken August 15, 2019 one month after application and after SPF removal.

Meter type	Location Zero (on block)		Location 5 (on wood beam)		Location 5 (on wood sill)	
	under SPF	w/o SPF	under SPF	w/o SPF	under SPF	w/o SPF
Delmhorst	NA	30+	28	20	30+	24
Protimeter	NA	14-17	32	20	30	24
tramex	NA	17.5	20+	20+	20+	20+
Ryobi	NA	33	100	26	100	34
Termatrac T3i	NA	29-30+	18	28-30+	23	30+
Laser temp °C	NA	26.7	27.4	28.2	26.8	27.4

Meter type	Location 20 (on block)		Location 15 (on wood beam)		Location 15 (on wood sill)	
	under SPF	w/o SPF	under SPF	w/o SPF	under SPF	w/o SPF
Delmhorst	NA	24	28	20	30+	24
Protimeter	NA	15-18	28	22	50	24
tramex	NA	18	20+	20+	20+	20+
Ryobi	NA	51	100	24	100	32-34
Termatrac T3i	NA	30+	27	30+	25	30+
Laser temp °C	NA	27.3	26.3	26.8	26.2	26.3

Table 2. Summary of locations (indicated by placement of ‘red arrows’) associated with observation of termite activity by inspection date and inspector/method.

Device/method used to identify termite activity by Inspector	Number of red arrows (signs of termite activity)		
	July 16 Before SPF application	July 17 No SPF On SPF	
Visual; Inspector #1	14	14	0
Visual/ IR Camera; Inspector #2	3	0	0
Termatrac T3i; Inspector #3	6	11	6
Visual; Inspector #4	5	5	0
Visual; Inspector #5	10	9	0

Appendix 1.

Photograph 1. Images taken during the September 6th, 2019 renovations showing the termite activity, by the red arrows, along the block foundation wall behind the joist header in the southeast corner of crawlspace at locations 0 and 5. The infestation likely accessed the structural lumber from the expansion joint between the slab and block wall (green arrow).



Photograph 2. Pictures of the floor joists between Locations 10 & 15 exposed during renovations conducted 6 September 2019. Pictures of each joist are arranged, left-to-right, by proximity to the joist header (on the left in this image) along the south wall of the crawlspace.







Spray Foam Insulation & Pest Management

The Georgia Structural Pest Control Commission (SPCC) serves the public by adopting regulations and policy to protect the health, safety and welfare of the citizens of Georgia. As part of their mission, the SPCC works with GDA to educate the public about structural pest management. This document was created to provide a background on spray foam insulation and issues related to pest management.

Reference – Polyurethane Spray Foam Insulation (PSFI)

The following is important information for Georgia consumers related to ***Polyurethane Spray Foam Insulation***.

The Georgia Department of Agriculture ***does not*** regulate Polyurethane Spray Foam Applicators, but is responsible for regulating the Pest Management industry in Georgia. The Pest Management industry has noticed an increase in PSFI installations in the State of Georgia during routine inspections for wood destroying organisms and have brought this to the attention of the SPCC. This publication is an effort to inform consumers how PSFI products may adversely impact the ability to inspect for and control termites, carpenter ants, wood boring beetles, and other pests including rats and mice.

If you are considering the installation of PSFI or have already installed this product, we urge you to read the information below to understand the issues surrounding the unintended consequences associated with trying to make your home more energy efficient. The Georgia Department of Agriculture recommends that you contact your local county extension office and several Pest Management Professionals to fully understand how these products could affect your home's protection from pests. It is also very important to know if a polystyrene spray foam installation will impact your existing termite warranty.

Background:

Polyurethane spray foam insulation is an alternative to traditional building insulation such as fiberglass. It is a two-component mixture composed of isocyanate and polyol resin which comes together at the tip of application tool to form an expanding foam. The foam can be sprayed on to/into/under any number of construction features to provide insulation for a building.

Advantages/Disadvantages

There are reported advantages and disadvantages of PSFI insulation by the industry. Advantages include energy cost savings and disadvantages include higher installation cost and hidden water leaks. The SPCC also notes that PSFI prevents comprehensive performance of inspections for wood destroying organisms and creates possible conditions that may invalidate your termite warranty. The last two disadvantages are notes because spray foam insulation can hide evidence of pest activity. For a full list of advantages and disadvantages visit <https://www.greeninsulationtechnologies.com/advantages-disadvantages-foam.php>

Polystyrene Spray Foam Insulation, Termites and Other Pests

Insect and rodent pests such as termites, carpenter ants and rats can easily chew through spray foam insulation which also provides insulation benefits to those pest populations. The presence of such pests within or behind the PSFI makes visual inspection and control problematic, if not impossible.

Polystyrene spray foam insulation impairs the ability of pest management inspectors from performing a visual inspection for evidence of a pest infestation, intrusion or damage. There are currently no inspection tools that can overcome how PSFI prevents visual inspection for pests.

Georgia Structural Pest Control regulations require pest management inspectors to determine the presence or previous presence of infestations and report these findings for Official Wood Infestation Inspection Reports and related control warranties. These inspections will include a visual inspection and the sounding and/or probing of accessible areas.

Polystyrene Spray Foam Insulation and Fumigation

Research has been conducted on PSFI to determine if other chemicals damage the integrity of the foam insulation. Research is, however, lacking on how fumigation gasses interact with polystyrene spray foam insulation. The result is that there are no scientific studies that provide information on using fumigation to control pests found to be infesting building materials covered with PSFI. There also are no established post-fumigation, re-entry or re-occupancy times or post-occupancy ventilation needs.

Spray Foam and Termite Warranties:

Pest Management companies typically include language in their contracts that the installation of products that prevent visual inspection may negatively affect or void a termite warranty. The SPCC recommends homeowners contact their Pest Management provider or consult with one for a review of how installation of PSFI could impact their pest control contract.

Spray Foam Insulation & Termites publication by the American Chemistry Council (ACC) and Spray Polyurethane Foam Alliance (SPFA)

<https://polyurethane.americanchemistry.com/Spray-Foam-Insulation-and-Termites.pdf>

This publication does reference, on page 13, that Georgia has modified the model energy code to include a termite inspection strip above and below the foundation wall to expose the sill plate and lower band/rim joist for visual inspection. The SPCC has concerns about the general use and practicality of the inspection equipment referenced in Chapter II. Termite Inspection and Treatment. The SPCC Rules call for a visual inspection for wood destroying pests and the utility of using thermal imaging, moisture meters, microwave motion detection, gas or acoustic emissions, or trained dogs for detecting a pest infestation through PSFI have not been adequately tested. The following image shows installation of PSFI in a Georgia home that does not include the required termite inspection strip.

